

CONNECTOR INSTALLATION INSTRUCTIONS

## Amphe-PD<sup>™</sup> Gen 2 5.7mm




C10-766084-06

C10-766084-04

C10-766084-02




## Part 1: Package Contents




- 1: Plug housing
- 2: Terminal
- 3: Sleeve -- Not needed for 2AWG
- 4: Clip


## Part 2: Plug assembly

**Step 1:** 2AWG/4AWG/6AWG wire cutting stripping jacket




Step 2: Insert the cable and sleeve into the terminal hole and crimp (sleeve not needed for 2AWG)






Cable Size	Recommended Crimp Height (H)	Recommended Crimp Width (W)	Cable Pullout Force
2AWG	7.9±0.1mm	7.9±0.1mm	801.0N Min.
4AWG	8.8±0.1mm	8.8±0.1mm	623.0N Min.
6AWG	9.0±0.1mm	9.0±0.1mm	445.0N Min.

Recommended crimping tool: Terminal-specific crimping machine 2AWG /4AWG/6AWG





## Recommended tool: Heat gun




The heat shrink tubing full recovery temperature: 175 °C

**Step 4:** Install cable of crimped terminals past the retainer.



**Step 5:** Insert the terminal of the pressed wire into the housing with retainer.



Retainer and housing should be buckled in place